1 of 2 100% Find | Next

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0621, W0615, W0623, W0463, W0469, W0467, W0649, W	NA, Shetty Lyt, 1st Main Rd, 3rd Crs, 4th Crs, Vinayaka Lyt 4th Crs, Ambedkar Nagar Slum	Bagalagunte
Segment No.	**Total Length (m)**	
14/S-W0621/S040107	242.46	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	
1	12.55	77.498859	13.056885	77.498876	13.056998	vijalakshmi layout 7th cross	vijala layo cr
2	12.52	77.504173	13.056843	77.504186	13.056955	Bagalagunte main road 15th cros	Bagal mair 15th
3	8.17	77.507900	13.057757	77.507930	13.057825	mallasandra 1st main 2nd cross l/s	malla 1st m cro
4	10.95	77.507887	13.057621	77.507908	13.057525	mallasandra 1st main 2nd cross r/s	malla 1st m cro
5	10.49	77.507592	13.057773	77.507632	13.057859	mallasandra 1st main 1st cross r/s	malla 1st m cro
6	10.25	77.507589	13.057660	77.507616	13.057572	mallasandra 1st main 1st cross l/s	malla 1st m cro
7	12.73	77.503010	13.063399	77.503005	13.063284	sampangi ramayya layout 3rd cross	sam ram layo cr
8	14.46	77.502654	13.063331	77.502651	13.063201	sampangi	sam

Scanned by CamScanner

21/01/2020 20/01/2021

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Releas
M.Lakshminarayana		3735576.00
Phone No.	**E-Mail ID**	
9448481324		

Yes

Field Inspection Details

Number of Trees	Any Other Information	Name
42		chetan KM
Date of Inspection	**Remarks**	
09/10/2020	work completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte

Street ID	Street Name	Significant Landmark
W0621, W0615, W0623, W0463, W0469, W0467, W0649, W	NA, Shetty Lyt, 1st Main Rd, 3rd Crs, 4th Crs, Vinayaka Lyt 4th Crs, Ambedkar Nagar Slum	Bagalagunte

Segment No.	Total Length (m)
14/S-W0621/S040107	242.46

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	12.55	77.498859	13.056885	77.498876	13.056998	vijalakshmi layout 7th cross	vijalakshmi layout 7th cross
2	12.52	77.504173	13.056843	77.504186	13.056955	Bagalagunte main road 15th cros	Bagalagunte main road 15th cros
3	8.17	77.507900	13.057757	77.507930	13.057825	mallasandra 1st main 2nd cross l/s	mallasandra 1st main 2nd cross l/s
4	10.95	77.507887	13.057621	77.507908	13.057525	mallasandra 1st main 2nd cross r/s	mallasandra 1st main 1st cross r/s
5	10.49	77.507592	13.057773	77.507632	13.057859	mallasandra 1st main 1st cross r/s	mallasandra 1st main 1st cross r/s
6	10.25	77.507589	13.057660	77.507616	13.057572	mallasandra 1st main 1st cross l/s	mallasandra 1st main 1st cross l/s
7	12.73	77.503010	13.063399	77.503005	13.063284	sampangi ramayya layout 3rd cross	sampangi ramayya layout 3rd cross
8	14.46	77.502654	13.063331	77.502651	13.063201	sampangi ramayya layout 4th cross	sampangi ramayya layout 4th cross
9	14.95	77.498951	13.069245	77.499085	13.069277	VV layout 10th cross	VV layout 10th cross
10	16.90	77.495891	13.062379	77.495836	13.062236	Royal enclave	Royal enclave
11	16.50	77.492982	13.063331	77.493133	13.063354	VV layout govt school opp park	VV layout govt school opp park
12	9.46	77.493841	13.062374	77.493806	13.062453	VV layout govt school opp krishnappa house	VV layout govt school opp krishnappa house
13	10.49	77.494181	13.062421	77.494136	13.062505	VV layout 13th cross	VV layout 13th cross
14	8.60	77.494442	13.062481	77.494399	13.062547	manjunatha nagara anjanadri medicals	manjunatha nagara anjanadri medicals

one: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0621, W0615, W0623, W0463,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ

Scanned by CamScanner

15	11.00	77.493691	13.053043	77.493696	13.052943	ganapathi layout 4th cross	ganapathi layout 4th cross
16	11.91	77.495390	13.056470	77.495380	13.056577	ganapathi layout 3rd cross	ganapathi layout 3rd cross
17	9.85	77.495691	13.056413	77.495665	13.056502	ganapathi layout 2nd cross	ganapathi layout 2nd cross
18	9.61	77.495937	13.056371	77.495927	13.056457	manjunatha nagara,7th main,3rd cross	manjunatha nagara,7th main,3rd cross
19	10.51	77.495752	13.056031	77.495766	13.055937	manjunatha nagara,7th main,3rd cross	manjunatha nagara,7th main,3rd cross
20	9.85	77.495468	13.056063	77.495473	13.055974	manjunatha nagara,7th main,2nd cross	manjunatha nagara,7th main,2nd cross
21	10.71	77.495197	13.056107	77.495202	13.056011	manjunatha nagara,7th main,coconut garden	manjunatha nagara,7th main,coconut garden

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of culvert in bagalagunte ward no14	4000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Others	CULVERTS
Tender	**Work Details**	**Job No. / Work Code**
Tender		014-20-000001
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/W.O/513/2019-20	21/01/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
21/01/2020	20/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.Lakshminarayana		3735576.00
Phone No.	**E-Mail ID**	
9448481324		

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0621, W0615, W0623, W0463,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಡಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿ.ಜಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Scanned by CamScanner

Inspection Details

nber of Trees	Any Other Information	Name
		chetan KM

Date of Inspection	Remarks
09/10/2020	work completed

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿ.ಬಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0621, W0615, W0623, W0463,

Scanned by CamScanner